

## Table ENG-5. - Sanitary Facilities

Frederick County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
1B:					
Berks	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
				Seepage	1.00
				Slope	0.68
1C:					
Berks	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
2:					
Birdsboro	85	Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	0.71
		Restricted permeability	0.50	Seepage	0.50
		Flooding	0.40	Flooding	0.40
3B:					
Blairton	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	0.68
		Restricted permeability	1.00	Seepage	0.27
3C:					
Blairton	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	1.00	Seepage	0.27
4B:					
Buchanan	80	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	0.68
		Restricted permeability	0.50	Seepage	0.50

4C:

# Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
4C:					
Buchanan	80	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
5B:					
Carbo	85	Very limited		Very limited	
		Restricted permeability	1.00	Depth to hard bedrock	1.00
		Depth to bedrock	1.00	Slope	0.68
5C:					
Carbo	85	Very limited		Very limited	
		Restricted permeability	1.00	Depth to hard bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00
		Slope	0.37		
6C:					
Carbo	50	Very limited		Very limited	
		Restricted permeability	1.00	Depth to hard bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00
		Slope	0.16		
Oaklet	45	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.04		
Rock outcrop	3	Not Rated		Not Rated	
7C:					
Carbo	35	Very limited		Very limited	
		Restricted permeability	1.00	Depth to hard bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00
		Slope	0.16		
Oaklet	30	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.04		
Rock outcrop	25	Not Rated		Not Rated	

8B:

# Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
8B:					
Chilhowie	80	Very limited		Very limited	
		Restricted permeability	1.00	Depth to hard bedrock	1.00
		Depth to bedrock	1.00	Slope	0.68
8C:					
Chilhowie	75	Very limited		Very limited	
		Restricted permeability	1.00	Depth to hard bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00
		Slope	0.37		
9B:					
Clearbrook	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Content of large stones	0.88
		Restricted permeability	1.00	Slope	0.68
9C:					
Clearbrook	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	1.00	Content of large stones	0.88
10:					
Craigsville	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Filtering capacity	1.00	Seepage	1.00
		Content of large stones	0.57	Content of large stones	1.00
11C:					
Dekalb	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Slope	0.37	Seepage	1.00
12E:					
Dekalb	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
13B:					

## Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
13B:					
Frankstown	75	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
13C:					
Frankstown	75	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
13D:					
Frankstown	70	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
13E:					
Frankstown	70	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
14B:					
Frederick	45	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Poplimento	40	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.68
14C:					
Frederick	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Poplimento	40	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37		
14D:					
Frederick	50	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50

# Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
14D:					
Poplimento	45	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	1.00		
15C:					
Frederick	55	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Poplimento	30	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37		
15D:					
Frederick	60	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Poplimento	30	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	1.00		
15E:					
Frederick	60	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Poplimento	30	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	1.00		
16B:					
Frederick	40	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
Poplimento	35	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.68
Rock outcrop	3	Not Rated		Not Rated	

16C:

## Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
16C:					
Frederick	45	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Poplimento	35	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37		
Rock outcrop	3	Not Rated		Not Rated	
16D:					
Frederick	45	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Poplimento	40	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	1.00		
Rock outcrop	3	Not Rated		Not Rated	
17C:					
Frederick	30	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.04	Seepage	0.50
Poplimento	25	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.04		
Rock outcrop	25	Not Rated		Not Rated	
17E:					
Frederick	30	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
Poplimento	25	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	1.00		
Rock outcrop	25	Not Rated		Not Rated	

18B:

# Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
18B:					
Gainesboro	45	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
				Seepage	1.00
				Slope	0.68
Lehew	30	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Seepage	1.00
		Content of large stones	0.53	Slope	0.68
18C:					
Gainesboro	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
Lehew	35	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Content of large stones	0.53	Seepage	1.00
18D:					
Gainesboro	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Lehew	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
18E:					
Gainesboro	45	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Lehew	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00

19C:

# Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
19C:					
Gilpin	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
20B:					
Guernsey	85	Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	0.96
		Restricted permeability	1.00	Slope	0.68
				Seepage	0.27
20C:					
Guernsey	85	Very limited		Very limited	
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	1.00	Depth to saturated zone	0.96
		Slope	0.37	Seepage	0.27
21C:					
Hayter	75	Somewhat limited		Very limited	
		Slope	0.37	Slope	1.00
		Content of large stones	0.31	Seepage	1.00
				Content of large stones	1.00
21D:					
Hayter	80	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Content of large stones	0.31	Seepage	1.00
				Content of large stones	1.00
22C:					
Hayter	75	Somewhat limited		Very limited	
		Content of large stones	0.73	Slope	1.00
				Seepage	1.00
		Slope	0.37	Content of large stones	1.00
22D:					
Hayter	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Content of large stones	0.73	Seepage	1.00
				Content of large stones	1.00

22E:



## Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
22E:					
Hayter	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Content of large stones	0.73	Seepage	1.00
				Content of large stones	1.00
23C:					
Hazleton	75	Very limited		Very limited	
		Filtering capacity	1.00	Slope	1.00
		Slope	0.37	Seepage	1.00
23D:					
Hazleton	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
23E:					
Hazleton	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
24E:					
Hazleton	75	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
25C:					
Laidig	75	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Slope	0.37	Depth to saturated zone	1.00
25D:					
Laidig	75	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Slope	1.00	Slope	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
25E:					
Laidig	75	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Slope	1.00	Slope	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00

26C:

# Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
26C:					
Lehew	90	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Content of large stones	0.53	Seepage	1.00
26D:					
Lehew	90	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
26E:					
Lehew	90	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
27:					
Library	90	Very limited		Very limited	
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Ponding	1.00
		Ponding	1.00	Slope	0.68
28:					
Lobdell	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage	1.00
29:					
Massanetta	90	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage	0.50
30B:					
Monongahela	85	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Depth to hard bedrock	0.93
		Depth to bedrock	0.98	Slope	0.68

## Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
31B:					
Nicholson	85	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Slope	0.68
				Seepage	0.50
32B:					
Oaklet	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.68
32C:					
Oaklet	75	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37		
33C:					
Opequon	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	0.04	Slope	1.00
				Seepage	0.27
Chilhowie	40	Very limited		Very limited	
		Restricted permeability	1.00	Depth to hard bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00
		Slope	0.04		
Rock outcrop	3	Not Rated		Not Rated	
33E:					
Opequon	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	0.27
Chilhowie	40	Very limited		Very limited	
		Restricted permeability	1.00	Depth to hard bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00
		Slope	1.00		
Rock outcrop	3	Not Rated		Not Rated	
34:					

## Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
34:					
Pagebrook	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00		
35:					
Pagebrook	95	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00		
36:					
Pits	100	Not Rated		Not Rated	
37D:					
Schaffemaker	90	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Slope	1.00	Seepage	1.00
37E:					
Schaffemaker	90	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
38B:					
Sequoia	80	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	1.00	Slope	0.68
38C:					
Sequoia	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Restricted permeability	1.00	Slope	1.00
		Slope	0.37		
38D:					
Sequoia	75	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
		Restricted permeability	1.00		

# Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
39B:					
Swimley	90	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
39C:					
Swimley	90	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
40B:					
Timberville	80	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Restricted permeability	0.50	Slope	0.68
				Seepage	0.50
41B:					
Weikert	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
				Seepage	1.00
				Slope	0.68
Berks	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
				Seepage	1.00
				Slope	0.68
41C:					
Weikert	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
Berks	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
41D:					
Weikert	55	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Berks	35	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00

41E:

## Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
41E:					
Weikert	60	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Berks	30	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
42C:					
Weikert	50	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
Berks	40	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	0.37	Slope	1.00
				Seepage	1.00
42D:					
Weikert	55	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Berks	35	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
42E:					
Weikert	60	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Berks	30	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
43:					
Wheeling	80	Very limited		Very limited	
		Filtering capacity	1.00	Seepage	1.00
		Restricted permeability	0.50	Flooding	0.40
		Flooding	0.40		

# Table ENG-5. - Sanitary Facilities - Continued

Frederick County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
44B:					
Zoar	75	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.68
		Depth to saturated zone	1.00	Depth to saturated zone	0.25
44C:					
Zoar	75	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	0.25
		Slope	0.37		
DAM:					
Dam	100	Not Rated		Not Rated	
W:					
Water	100	Not Rated		Not Rated	